

*Easy Search*

	Type	L #	Hits	Search Text	DBs	Time Stamp
1	BRS	L3	384	(method with fastener).TI. and molding	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/12 03:50
2	BRS	L4	81	3 and (hook with loop)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/12 03:49
3	BRS	L5	2009	leach.INV.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/12 03:49
4	BRS	L6	42	5 and (hook and loop)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/12 03:49
5	BRS	L7	2891	(method with fastener) and molding	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/12 03:50
6	BRS	L8	578	7 and (hook and loop)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/12 03:50
7	BRS	L9	418	8 and base	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/12 03:50
8	BRS	L10	65	9 and neck	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/12 03:51
9	BRS	L11	0	(method with velcro with fastener).TI. and molding	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/12 03:52

	Comments	Error Definition	Error s
1			0
2			0
3			0
4			0
5			0
6			0
7			0
8			0
9			0

	Type	L #	Hits	Search Text	DBs	Time Stamp
10	BRS	L12	3	(method with velcro with fastener).TI.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/12 03:53

	Comments	Error Definition	Errors
10			0